



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


|                       |   |                  |          |                              |         |
|-----------------------|---|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 3 | <b>Date:</b>     | 8/9/2004 | <b>MeterBasin:</b>           | 01_WR13 |
| <b>Observer ID:</b>   | A | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 4 | <b>Setup No:</b> | 3        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2418                |                       | Briarwood           | ROAD                |

|                     |              |                       |              |                  |
|---------------------|--------------|-----------------------|--------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 25           |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 28

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0809-2004\T-1\PLAYER\_A\2004\_0809Image0028.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

3

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\3.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


|                       |   |                  |          |                              |         |
|-----------------------|---|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 3 | <b>Date:</b>     | 8/9/2004 | <b>MeterBasin:</b>           | 01_WR13 |
| <b>Observer ID:</b>   | B | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 1 | <b>Setup No:</b> | 3        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2409                |                       | Briarwood           | ROAD                |

|                     |              |                       |              |                  |
|---------------------|--------------|-----------------------|--------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 20           |                  |

**Comments:** Hole in the ground

## SMOKE TEST PHOTOS



**Photo No:** 21

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0809-2004\T-1\PLAYER\_A\2004\_0809Image0021.JPG

**Image Status:** Image found and displayed.



**Photo No:** 22

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0809-2004\T-1\PLAYER\_A\2004\_0809Image0022.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 3

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\3.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |          |                              |         |
|-----------------------|---|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 3 | <b>Date:</b>     | 8/9/2004 | <b>MeterBasin:</b>           | 01_WR13 |
| <b>Observer ID:</b>   | B | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 2 | <b>Setup No:</b> | 3        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2409                |                       | Briarwood           | ROAD                |

|                     |           |                       |        |                  |
|---------------------|-----------|-----------------------|--------|------------------|
| <b>Source Type:</b> | 18= Other | <b>Location:</b>      | 6=Curb | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private | <b>Drainage Area:</b> | 0      |                  |

**Comments:** Drain pipe on curb

## SMOKE TEST PHOTOS



**Photo No:** 23

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0809-2004\T-1\PLAYER\_A\2004\_0809Image0023.JPG

**Image Status:** Image found and displayed.



**Photo No:** 24

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0809-2004\T-1\PLAYER\_A\2004\_0809Image0024.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 3

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\3.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |          |                              |         |
|-----------------------|---|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 4 | <b>Date:</b>     | 8/9/2004 | <b>MeterBasin:</b>           | 01_WR12 |
| <b>Observer ID:</b>   | A | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | Y       |
| <b>Defect No:</b>     | 1 | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                 |                       |        |                     |             |                     |     |
|---------------------|-----------------|-----------------------|--------|---------------------|-------------|---------------------|-----|
| <b>House Number</b> | 5800            | <b>Street Prefix:</b> |        | <b>Street Name:</b> | Greenspring | <b>Street Type:</b> | AVE |
| <b>Source Type:</b> | 14= Catch Basin | <b>Location:</b>      | 6=Curb | <b>Severity:</b>    |             |                     |     |
| <b>Sector:</b>      | 1=Public        | <b>Drainage Area:</b> | 5200   |                     |             |                     |     |
| <b>Comments:</b>    | Storm drain     |                       |        |                     |             |                     |     |

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 29

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0809-2004\T-1\PLAYER\_A\2004\_0809Image0029.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

4

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\4.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |          |                              |         |
|-----------------------|---|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 4 | <b>Date:</b>     | 8/9/2004 | <b>MeterBasin:</b>           | 01_WR13 |
| <b>Observer ID:</b>   | A | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 2 | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |              |                       |              |                     |            |                     |      |
|---------------------|--------------|-----------------------|--------------|---------------------|------------|---------------------|------|
| <b>House Number</b> | 5722         | <b>Street Prefix:</b> |              | <b>Street Name:</b> | Rockspring | <b>Street Type:</b> | ROAD |
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b>    |            |                     |      |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 25           |                     |            |                     |      |
| <b>Comments:</b>    |              |                       |              |                     |            |                     |      |

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 30

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0809-2004\T-1\PLAYER\_A\2004\_0809Image0030.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

4

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\4.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |          |                              |         |
|-----------------------|---|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 4 | <b>Date:</b>     | 8/9/2004 | <b>MeterBasin:</b>           | 01_WR13 |
| <b>Observer ID:</b>   | A | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 3 | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |              |                       |              |                     |            |                     |      |
|---------------------|--------------|-----------------------|--------------|---------------------|------------|---------------------|------|
| <b>House Number</b> | 5733         | <b>Street Prefix:</b> |              | <b>Street Name:</b> | Rockspring | <b>Street Type:</b> | ROAD |
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b>    |            |                     |      |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 25           |                     |            |                     |      |
| <b>Comments:</b>    |              |                       |              |                     |            |                     |      |

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 31

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0809-2004\T-1\PLAYER\_A\2004\_0809Image0031.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

4

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\4.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*




# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |          |                              |         |
|-----------------------|---|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 4 | <b>Date:</b>     | 8/9/2004 | <b>MeterBasin:</b>           | 01_WR13 |
| <b>Observer ID:</b>   | A | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 4 | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |              |                       |              |                     |            |                     |      |
|---------------------|--------------|-----------------------|--------------|---------------------|------------|---------------------|------|
| <b>House Number</b> | 5739         | <b>Street Prefix:</b> |              | <b>Street Name:</b> | Rockspring | <b>Street Type:</b> | ROAD |
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b>    |            |                     |      |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 25           |                     |            |                     |      |
| <b>Comments:</b>    |              |                       |              |                     |            |                     |      |

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 32

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0809-2004\T-1\PLAYER\_A\2004\_0809Image0032.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

4

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\4.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |          |                              |         |
|-----------------------|---|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 4 | <b>Date:</b>     | 8/9/2004 | <b>MeterBasin:</b>           | 01_WR13 |
| <b>Observer ID:</b>   | A | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 5 | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 5724                |                       | Rockspring          | ROAD                |

|                     |                       |                       |          |                  |
|---------------------|-----------------------|-----------------------|----------|------------------|
| <b>Source Type:</b> | 11= Building Interior | <b>Location:</b>      | 14=Other | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private             | <b>Drainage Area:</b> | 0        |                  |
| <b>Comments:</b>    | Basement sink         |                       |          |                  |

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

4

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\4.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |          |                              |         |
|-----------------------|---|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 4 | <b>Date:</b>     | 8/9/2004 | <b>MeterBasin:</b>           | 01_WR12 |
| <b>Observer ID:</b>   | B | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 1 | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2401                |                       | Crest               | ROAD                |

|                     |              |                       |              |                  |
|---------------------|--------------|-----------------------|--------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 25           |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 25

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0809-2004\T-1\PLAYER\_B\2004\_0809Image0025.JPG

**Image Status:** Image found and displayed.



**Photo No:** 26

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0809-2004\T-1\PLAYER\_B\2004\_0809Image0026.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

4

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\4.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |          |                              |         |
|-----------------------|---|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 4 | <b>Date:</b>     | 8/9/2004 | <b>MeterBasin:</b>           | 01_WR12 |
| <b>Observer ID:</b>   | B | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | Y       |
| <b>Defect No:</b>     | 2 | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2401                |                       | Crest               | ROAD                |

|                     |                 |                       |        |                  |         |
|---------------------|-----------------|-----------------------|--------|------------------|---------|
| <b>Source Type:</b> | 14= Catch Basin | <b>Location:</b>      | 6=Curb | <b>Severity:</b> | 4=Major |
| <b>Sector:</b>      | 1=Public        | <b>Drainage Area:</b> | 5200   |                  |         |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 27

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0809-2004\T-1\PLAYER\_B\2004\_0809Image0027.JPG

**Image Status:** Image found and displayed.



**Photo No:** 28

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0809-2004\T-1\PLAYER\_B\2004\_0809Image0028.JPG

**Image Status:** Image found and displayed.



**Photo No:** 29

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0809-2004\T-1\PLAYER\_B\2004\_0809Image0029.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

4

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\4.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |           |                              |         |
|-----------------------|---|------------------|-----------|------------------------------|---------|
| <b>Unique Test ID</b> | 5 | <b>Date:</b>     | 8/10/2004 | <b>MeterBasin:</b>           | 01_WR12 |
| <b>Observer ID:</b>   | A | <b>Crew:</b>     | T-1       | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 1 | <b>Setup No:</b> | 1         | <b>Priority CCTV:</b>        |         |

|                     |                       |                       |                     |
|---------------------|-----------------------|-----------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b>   | <b>Street Type:</b> |
| 5734                |                       | Greenspring           | AVE                 |
| <b>Source Type:</b> | 04= Cleanout          | <b>Location:</b>      | 7=Yard-Front        |
| <b>Sector:</b>      | 2=Private             | <b>Drainage Area:</b> | 25                  |
| <b>Comments:</b>    |                       |                       |                     |

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 1

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_A(A)2004\_0810Image0001.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

5

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\5.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |           |                              |         |
|-----------------------|---|------------------|-----------|------------------------------|---------|
| <b>Unique Test ID</b> | 5 | <b>Date:</b>     | 8/10/2004 | <b>MeterBasin:</b>           | 01_WR12 |
| <b>Observer ID:</b>   | A | <b>Crew:</b>     | T-1       | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 2 | <b>Setup No:</b> | 1         | <b>Priority CCTV:</b>        |         |

|                     |              |                       |              |                     |             |                     |     |
|---------------------|--------------|-----------------------|--------------|---------------------|-------------|---------------------|-----|
| <b>House Number</b> | 5732         | <b>Street Prefix:</b> |              | <b>Street Name:</b> | Greenspring | <b>Street Type:</b> | AVE |
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b>    |             |                     |     |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 25           |                     |             |                     |     |
| <b>Comments:</b>    |              |                       |              |                     |             |                     |     |

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_A(A)2004\_0810Image0002.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

5

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\5.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |           |                              |         |
|-----------------------|---|------------------|-----------|------------------------------|---------|
| <b>Unique Test ID</b> | 5 | <b>Date:</b>     | 8/10/2004 | <b>MeterBasin:</b>           | 01_WR12 |
| <b>Observer ID:</b>   | A | <b>Crew:</b>     | T-1       | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 3 | <b>Setup No:</b> | 1         | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 5726                |                       | Greenspring         | AVE                 |

|                     |              |                       |              |                  |
|---------------------|--------------|-----------------------|--------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 25           |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_A\A)2004\_0810Image0003.JPG

**Image Status:** Image found and displayed.



**Photo No:** 4

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_A\A)2004\_0810Image0004.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



**Sketch No:**

5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\5.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |           |                              |         |
|-----------------------|---|------------------|-----------|------------------------------|---------|
| <b>Unique Test ID</b> | 5 | <b>Date:</b>     | 8/10/2004 | <b>MeterBasin:</b>           | 01_WR12 |
| <b>Observer ID:</b>   | B | <b>Crew:</b>     | T-1       | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 1 | <b>Setup No:</b> | 1         | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 5738                |                       | Greenspring         | AVE                 |

|                     |              |                       |              |                  |
|---------------------|--------------|-----------------------|--------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 30           |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_B(B)2004\_0810Image0002.JPG

**Image Status:** Image found and displayed.



**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_B(B)2004\_0810Image0003.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

5

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\5.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |           |                              |         |
|-----------------------|---|------------------|-----------|------------------------------|---------|
| <b>Unique Test ID</b> | 5 | <b>Date:</b>     | 8/10/2004 | <b>MeterBasin:</b>           | 01_WR12 |
| <b>Observer ID:</b>   | B | <b>Crew:</b>     | T-1       | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 2 | <b>Setup No:</b> | 1         | <b>Priority CCTV:</b>        |         |

|                     |                       |                       |                     |
|---------------------|-----------------------|-----------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b>   | <b>Street Type:</b> |
| 5734                |                       | Greenspring           | AVE                 |
| <b>Source Type:</b> | 04= Cleanout          | <b>Location:</b>      | 7=Yard-Front        |
| <b>Sector:</b>      | 2=Private             | <b>Drainage Area:</b> | 25                  |
| <b>Comments:</b>    |                       |                       |                     |

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 4

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\0810-2004\T-1\PLAYER\_B(B)2004\_0810Image0004.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

5

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\5.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |           |                              |         |
|-----------------------|---|------------------|-----------|------------------------------|---------|
| <b>Unique Test ID</b> | 5 | <b>Date:</b>     | 8/10/2004 | <b>MeterBasin:</b>           | 01_WR12 |
| <b>Observer ID:</b>   | B | <b>Crew:</b>     | T-1       | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 3 | <b>Setup No:</b> | 1         | <b>Priority CCTV:</b>        |         |

|                     |                       |                       |                     |
|---------------------|-----------------------|-----------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b>   | <b>Street Type:</b> |
| 5734                |                       | Greenspring           | AVE                 |
| <b>Source Type:</b> | 04= Cleanout          | <b>Location:</b>      | 7=Yard-Front        |
| <b>Sector:</b>      | 2=Private             | <b>Drainage Area:</b> | 25                  |
| <b>Comments:</b>    |                       |                       |                     |

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_B(B)2004\_0810Image0005.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



**Sketch No:**

5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\5.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |           |                              |         |
|-----------------------|---|------------------|-----------|------------------------------|---------|
| <b>Unique Test ID</b> | 6 | <b>Date:</b>     | 8/10/2004 | <b>MeterBasin:</b>           | 01_WR12 |
| <b>Observer ID:</b>   | B | <b>Crew:</b>     | T-1       | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 1 | <b>Setup No:</b> | 2         | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 5715                |                       | Greenspring         | AVE                 |

|                     |              |                       |              |                  |
|---------------------|--------------|-----------------------|--------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 15           |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 6

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_B(B)2004\_0810Image0006.JPG

**Image Status:** Image found and displayed.



**Photo No:** 7

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_B(B)2004\_0810Image0007.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

6

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\6.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


|                       |   |                  |           |                              |         |
|-----------------------|---|------------------|-----------|------------------------------|---------|
| <b>Unique Test ID</b> | 6 | <b>Date:</b>     | 8/10/2004 | <b>MeterBasin:</b>           | 01_WR12 |
| <b>Observer ID:</b>   | B | <b>Crew:</b>     | T-1       | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 2 | <b>Setup No:</b> | 2         | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 5707                |                       | Greenspring         | AVE                 |

|                     |              |                       |              |                  |
|---------------------|--------------|-----------------------|--------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 25           |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 8

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_B(B)2004\_0810Image0008.JPG

**Image Status:** Image found and displayed.



**Photo No:** 9

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_B(B)2004\_0810Image0009.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

6

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\6.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


|                       |   |                  |           |                              |         |
|-----------------------|---|------------------|-----------|------------------------------|---------|
| <b>Unique Test ID</b> | 6 | <b>Date:</b>     | 8/10/2004 | <b>MeterBasin:</b>           | 01_WR12 |
| <b>Observer ID:</b>   | B | <b>Crew:</b>     | T-1       | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 3 | <b>Setup No:</b> | 2         | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 5710                |                       | Greenspring         | AVE                 |

|                     |              |                       |              |                  |
|---------------------|--------------|-----------------------|--------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 10           |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 10

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_B(B)2004\_0810Image0010.JPG

**Image Status:** Image found and displayed.



**Photo No:** 11

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_B(B)2004\_0810Image0011.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

6

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\6.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |   |                  |           |                              |   |
|-----------------------|---|------------------|-----------|------------------------------|---|
| <b>Unique Test ID</b> | 7 | <b>Date:</b>     | 8/10/2004 | <b>MeterBasin:</b>           |   |
| <b>Observer ID:</b>   | A | <b>Crew:</b>     | T-1       | <b>Dye Test Recommended:</b> | N |
| <b>Defect No:</b>     | 1 | <b>Setup No:</b> | 3         | <b>Priority CCTV:</b>        |   |

|                     |              |                       |              |                     |             |                     |     |
|---------------------|--------------|-----------------------|--------------|---------------------|-------------|---------------------|-----|
| <b>House Number</b> | 5700         | <b>Street Prefix:</b> |              | <b>Street Name:</b> | Greenspring | <b>Street Type:</b> | AVE |
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b>    |             |                     |     |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 25           |                     |             |                     |     |
| <b>Comments:</b>    |              |                       |              |                     |             |                     |     |

## SMOKE TEST PHOTOS



**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0810-2004\T-1\PLAYER\_A(A)2004\_0810Image0005.JPG

**Image Status:** Image found and displayed.

**Photo No:**  
**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No:

7

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\7.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.